



INSTALL ROADTRACER PRO (2.1 minimum) on WINDOWS 10 with Tripy RoadMaster I (TRMI) (GPS Tripy = hardware key)


- Follow procedure to disable 'driver signature enforcement' see at <http://www.howtogeek.com/167723/how-to-disable-driver-signature-verification-on-64-bit-windows-8.1-so-that-you-can-install-unsigned-drivers/>
- Connect Tripy I to computer
- Wait 30 seconds
- Open Device Manager by selecting 'Settings' in start menu and entering 'device manager' in 'find a setting' field and press 'enter'



- Left click on Tripy Cable icon (normally accompanied by a yellow exclamation mark icon)
- Select Update Driver Software



- Select option 'Browse my computer for driver software' in the next screen



← Update Driver Software - Tripy Cable

Browse for driver software on your computer

Search for driver software in this location:

C:\Program Files (x86)\Tripy\Road Tracer\driver

Browse...

Include subfolders

← Update Driver Software - Tripy Cable

→ Let me pick
This list will show
software in the s

Windows has successfully updated your driver software

Windows has finished installing the driver software for this device:



Tripy Cable

Close

×

- When driver is correctly installed, the following screen will appear :